

COMPLETION CUM STRUCTURAL STABILITY
CERTIFICATE OF BUILDING AND PUGCA BOUNDARY WALL

I, Sri Achutananda Patra, Junior Engineer, Minor Irrigation Section, Buguda hereby certified that the Shree Krishna International School, 96, Malipada, Bhubaneswar, Odisha have personally inspected and found the (G+1) school building has been completed with safe structure and surrounded by Pucca boundary and iron gate.

APd
19/11/18
Junior Engineer
Minor Irrigation Section,
Buguda

ER. Santosh Kumar Sahoo
 B.E.(Civil)/M.E. (Structure)
 Bhubaneswar Development Authority, Odisha,
 Registered Structural Engineer, Bhubaneswar.

STRUCTURAL STABILITY CERTIFICATE

This is certify that I Sri Er. Santosh Kumar Sahoo, have prepared this structural design for the academic block and hostel block of Srikrishna International School at Malipada, Bhubaneswar as per the provision of National Building Code. I undertake the responsibility with regards to periodical supervision of the work at each stage of construction (after laying of foundation and after casting of each floor) and submit the report to concerned authority to the effect that the building is being constructed as per the structural design prepared by me/firm as per the provisions of NBC taking into account the safety factors like Cyclone and earth quake etc. I will be responsible and liable for action by concern authority. If the plan/ design submitted contained misrepresentation of fraudulent statement of fact and if there is any structural failure.

Santosh Kumar Sahoo
 13/10/18
 Signature and Seal

ER. SANTOSH KUMAR SAHOO
 B.E. (CIVIL), M.E. (STRUCTURE)
 BDA REGISTERED STRUCTURAL ENGINEER
 BDA REGD. NO. - 52811/2011

[Signature]
 Counter Signature of

Plot owner / owners & developer

